

# DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



Michael O. Leavitt Governor

Kathleen Clarke Executive Director

Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340

801-359-3940 (Fax)

Partial: X Complete:\_\_ Exploration: Inspection Date & Time 1.50

Date of Last Inspection: 12/9/99

Division Director 801-538-7223 (TDD)				•
Mine Name: Horse Canyon Mine County: Carbo	on Permit Nun	nber:	AND 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Permittee and/or Operator's Name: <u>Utah American</u>				
•	Energy, me.			
Business Address: P.O. Box 986 Price, Utah 84501		_		
Type of Mining Activity: Underground X Surfa	ce Prep. Plant	(	Other	
State Officials(s): Susan White				
Company Official(s): Paul Clark				
Federal Official(s):				
Weather Conditions: Cloudy turning to partly cloud	У			
Existing Acreage: Permitted-71 Disturbed-71 Regularity	raded-59 Seeded	-59 B	onded-71	
Increased/Decreased: Permitted Disturbed				
	_			
Status: _Exploration/_Active/_Inactive/_Tempor				
Reclamation (_Phase I/_Phase II/_Final Bo	ond Release/Liab	oility_	<u>Year</u> )	
REVIEW OF PERMIT, PERFORMANCE STANDARD	OS & PERMIT CONDITI	ON REC	QUIREMENTS	
Instructions				
<ol> <li>Substantiate the elements on this inspection by checking the appropria. For complete inspections provide narrative justification for any experiments.</li> </ol>	oriate performance standar	d. Lumbaga e	alament is not appropris	te to the
site, in which case check N/A.	nements not runy hispected	umess	mement is not appropria	ac to the
b. For <u>partial inspections</u> check only the elements evaluated.				
2. Document any noncompliance situation by referencing the NOV is:	sued at the appropriate per	rforman	ce standard listed belo	w.
3. Reference any narratives written in conjunction with this inspection	at the appropriate perfor	mance s	tandard listed below.	
4. Provide a brief status report for all pending enforcement actions, pe				NIOW/ENIE
1 DEDMITS CHANCE TRANSPER DENEWAL CALE	EVALUATED	<u>N/A</u>	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE 2. SIGNS AND MARKERS	[X] [X]	井	[X] [X]	<del>     </del>
3. TOPSOIL	[ <u>A</u> ]	Η	[ ]	낡
4. HYDROLOGIC BALANCE:	₩.	<u></u>	₩.	
a. DIVERSIONS	[X]	r 1	[X]	r 1
b. SEDIMENT PONDS AND IMPOUNDMENTS	· []	H	[]	Ħ
c. OTHER SEDIMENT CONTROL MEASURES	Ti -	Ħ	ī	īi
d. WATER MONITORING	ii	Ħ	īī	$\Box$
e. EFFLUENT LIMITATIONS	Ξ	$\Box$	· 🗇	
5. EXPLOSIVES		$\Box$		$\Box$
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	$\Box$	П	Ü	$\Box$
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	$\Box$	Ш		$\Box$
8. NONCOAL WASTE	$\Box$	$\Box$	$\Box$	$\Box$
9. PROTECTION OF FISH, WILDLIFE AND				
RELATED ENVIRONMENTAL VALUES	[X]	Ц	Ц	ĻĻ
10. SLIDES AND OTHER DAMAGE	Ļ	ĻŢ	Ц	H
11. CONTEMPORANEOUS RECLAMATION	L.	ĻĻ	H	H
12. BACKFILLING AND GRADING		ᆛ	H	片
<ul><li>13. REVEGETATION</li><li>14. SUBSIDENCE CONTROL</li></ul>	ĮΔĮ	누	<del>[ ]</del>	
<ul><li>14. SUBSIDENCE CONTROL</li><li>15. CESSATION OF OPERATIONS</li></ul>	<del>     </del>	분	<u>                                     </u>	<del>     </del>
16. ROADS:	. 📙	11	ш	11
a. CONSTRUCTION/MAINTENANCE/SURFACING	r 1	гэ	r 1.	r 1
b. DRAINAGE CONTROLS	<u> </u>	<del>   </del>	[]	7
17. OTHER TRANSPORTATION FACILITIES	H	11	H	Ħ
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	ΙΧΊ	<u>†</u> †	ΪΧΊ	Ħ
19. AVS CHECK (4th Quarter-April, May, June) (date)	يشقياً أ	Ħ	[ ]	ij
20. AIR QUALITY PERMIT		$\Box$	Π	$\Box$
21. BONDING & INSURANCE		ΙĨ	ĹĨ	$\Box$

#### INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/007/013

DATE OF INSPECTION: 1/27/99

(Comments are Numbered to Correspond with Topics Listed Above)

# 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

A new Operator, Utah American Energy, Inc., for the mine has been approved by the Division.

The mid-term review identified two permit items requiring correction; 1) drainage from facilities area into pond 2 and 2) identifying areas other than the borrow pit to obtain fill for final reclamation. These issues were required a response the Division by February 22, 1999.

#### 2. SIGNS AND MARKERS

Mr. Clark stated that he had just received the specifications for the new permit identification signs and was ordering the signs.

### 4. HYDROLOGIC BALANCE:

The drainage from the facilities area to Sediment Pond #2 appeared in suitable condition. However Mr. Clark was advised that the drainage would need to be watched and repaired if needed to maintain proper drainage.

## 18. SUPPORT FACILITIES/UTILITIES INSTALLATIONS

The facilities area was walked. The inside and outsides of the buildings appeared in good condition. The new Operator is reminded that a historic resources inventory is required of the buildings prior to any alterations or demolition.

Roof tiles on the buildings are asbestos and will required special handling if or when demolished.

Copy of this Report:

Mailed to: OSM, Jay Marshall (UAE), William W. Engels (IPA), Paul Clark

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Second M. White #35 Date: 1/27/99